


AUTOMATIC MODE OPERATION:

- 1. WHEN SENSOR ACTIVATES, BOTH LOADS TURN ON.
- 2. LOADS TURN OFF WHEN SENSOR TIMES OUT.

RECOMMENDED WIRE:  
18-3 AWG STRANDED WIRE SHIELDED OR NONSHIELDED



\*\*USE BLACK LEAD FOR 120VAC.  
USE ORANGE LEAD FOR 277VAC.  
CAP UNUSED LEAD.

NOTES

- 1. SPD20-MV-NO SWITCHPACK SHOWN, 120/277VAC 20AMP RATING PER RELAY.
- 2. BLUE AND RED WIRE LEADS ARE NON-POLARITY SENSITIVE.

NOTES:  
1. SENSOR TYPE INCLUDE OAC-P-0500, OAC-P-1500, OAC-U-0501, OAC-U-1000, OAC-U-2000, OAC-DT-0501, OAC-DT-1000, OAC-DT-2000.  
2. SPD20-MV-NO SWITCHPACK SHOWN. REFER TO CUT SHEETS AND/OR INSTALLATION INSTRUCTIONS FOR OTHER GREENGATE SWITCHPACK WIRING.



Tel: 1-800-553-3879  
Fax: 1-800-954-7016  
Addr: 203 Cooper Circle  
Peachtree City, GA 30269, USA  
ControlsSales@cooperindustries.com  
www.coopercontrol.com

PROJECT			DRAWN BY		CHECKED BY		APPROVED BY	
CEILING SENSOR WIRING DIAGRAM			CHKBY		APPRBY			
TITLE			DATE		DWG NO.		REV.	
SINGLE SENSOR AUTO ON /OFF			05-29-2013		CI-1D1-2-0000-000		A	